



- H1 MountingHole
- H2 MountingHole
- H4 MountingHole

New Build 15

- 1) There was a short in C4 in the usb circuit, this was corrected
- 2) Removed pull up from lora pin 12
- 3) Removed low side switch and added TPS2051BDBVR to switch on the high side
- 4) Changed R10 and R11 to 47k
- 5) Reworked the jumpers for the usb. deleted the mosfet and added a voltage divider to be the input to the esp32

Digital Stables
 Sheet: /
 File: Pancho.sch

Title: Pancho

Size: A4 Date: 2025-05-07
 KiCad E.D.A. kicad 5.1.5+dfsg1-2build2

Rev: 15
 Id: 1/1